

**1979 Piper PA-28-181 Archer II**  
**AIRCRAFT SPECIFICATIONS**  
**N-Number: N2823L S/N: 28-7990476**

Very attractive, hard-to-find Archer II with quiet interior. Just 394 hours on Lycoming O-360-A4M with 180 horsepower. Solid old school Collins IFR panel is a good upgrade candidate. Great performance and platform for training or travel.

**Airframe: 6,476 Hours**  
**Engine: 394 Hours SMOH**  
**PROP: 377 HOURS SNEW**

**Avionics**

Collins AMR-350 Audio Panel/ Marker Beacon  
Collins VHF-251 COMM (2)  
Collins VIR-351 NAV  
Collins VIR-350 NAV  
King KN62A DME  
Collins ADF-650  
King KT76A Mode C Transponder  
Collins IND-351A VOR/LOC/GS Indicator  
Collins IND-350 VOR/LOC Indicator  
Garmin GPSMAP 296  
Sigtronics SPA-400 4-place Intercom  
Hours Meter  
12v Power Outlet

**Features**

Electric Pitch Trim  
Brackett Air filter  
Includes 4 Lightspeed 15XLc ANR Headsets

Engine  
Lycoming O-360-A4M / 2000 TBO  
S/N: L-25525-36A  
7/2008 Overhaul

Propeller  
Sensenich  
Model: 76EM8S5-060/ TBO  
Hub S/N: 100734K  
7/2008 new

**Interior**

2005 interior  
Light gray fabric seating surfaces  
Zodiac gray vinyl seats and trim  
Light gray side panels  
Granite gray carpets  
Ensolute foam cabin insulations

**Exterior**

1989 Paint  
Overall Vestal White  
Triple stripe scheme with metallic medium and slate blues with gold

**Details**

Old History:  
03/2008 - Taxi incident; right wing damaged. FAA 337 and logbook entries of repairs available.

**Located at KPWT** ([KPWT Details](#))

Hangared All logs and records

Call Todd Huvad  
919.553.5235  
todd@aircraftmerchants.com  
www.aircraftmerchants.com



[See all Pictures and Details at www.aircraftmerchants.com](http://www.aircraftmerchants.com)