

# Call Todd Huvard 919.553.5235

todd@aircraftmerchants.com www.aircraftmerchants.com PO Box 1089 • Clayton, NC 27528

1979 Piper PA-32RT-300 Lance II **AIRCRAFT SPECIFICATIONS** 

N-Number: N2154E S/N: 32R-7985038

Very fast LoPresti-modified Lance II featuring Howl Cowl mod, dual Garmin 430 WAAS, Century IIIc autopilot and 3-blade Hartzell propeller. Factory air conditioning and great useful load of 1270 lbs. Beautiful paint and 6-place leather interior. Haul it all in comfort and style!

Airframe: 4,012 Hours

Engine: 2,196 Hours SMOH PROP: 56 HOURS SPOH

#### Avionics

Dual Garmin GNS-430W WAAS IFR GPS/Nav/Comm

- Garmin GI-106A GPS/VOR/LOC/GS Indicator (#2)
- Garmin Portable GPS Data-Out Interface Wiring
- Century NSD 360A HSI (#1)
- Slaved Compass System
- JPI Fuel Flow Interface to #1 430W

Century IIIC Autopilot

- Altitude Hold
- Electric Trim
- Glideslope Intercept

King KT-76A Mode C Transponder

· Altitude Encoder

King KMA-20 Audio Panel

Marker Beacons

BF Goodrich WX-900 Stormscope (INOP)

PS Engineering PM 1000 II 6-place Intercom

JPI EDM 800 Engine Monitor

Fuel Flow

Yoke Switching

- Pilot and Co-Pilot PTT
- Electric Trim
- **Autopilot Disconnect**

Castleberry Electric Standby Horizon

Alternate Static Source

Precise Flight Standby Vacuum

## Interior

Excellent Condition 6-Place Executive Interior

- Original Lance stowable writing desk
- Club Seating Main Cabin
- Refreshment Center Console
- Cabin Reading Lights

Tan leather seats with tan carpet

### Exterior

Beautiful new full strip and paint

Matterhorn White

Las Vegas Gold and Colonial Blue Full Length Custom Fuselage Cover

#### Features

Factory Air Conditioning

- Cabin Air Blower Hi/Lo

GAMI Fuel Injectors STC

Hartzell 3-blade prop STC

LoPresti Howl Cowl STC

LoPresti Zip Tip Wingtips STC

LoPresti Speed Seals (flap wing seals) LoPresti Spats (main wheel fairings)

LoPresti Splitters (flap hinge fairings)

LoPresti Hubba Hubba Cap

Whelen Parmetheus Plus LED Landing Light

Brackett Air Filter STC

Precise Flight Standby Vacuum STC

ADC Spin-On Oil Filter STC

Pilot and Co-Pilot Toe Brakes

Handheld Radio External Antennae Connection

Upgraded 1/4" windshield

Automatic Gear Extension System

## Details

Old History:

1992 - Gear up landing, all repairs documented in logs by FAA repair station Lowe Aviation, Macon, GA

June 2018 - FBO Tug damaged one propeller blade; required a propeller overhaul and engine IRAN, documented in logs

Engine time is beyond TBO and has now been taken out of service - must be replaced by Buyer after closing. We can assist you with an engine replacement, overhaul or factory rebuilt. Call for details.

## Located at KLHZ (KLHZ Details)

Hangared All logs and Records

Call Todd Huvard 919.553.5235

todd@aircraftmerchants.com www.aircraftmerchants.com







See all Pictures and Details at www.aircraftmerchants.com